

Swept Paths - Ref 665 – 145 Missenden Road, Camperdown

Swept paths under existing conditions show 12.5m bus turning left in kerbside lane from Carillon Avenue to Missenden Road has tail swing into centre lane.



Swept paths under proposed conditions show 12.5m bus needs to turn left from centre lane of Carillon Avenue to Missenden Road. Feedback is requested from bus operators on this proposal and regarding how bus drivers typically approach this turn under existing conditions.

