Attachment A

Fire Safety Reports Summary Sheet

Fire Safety Reports Summary Sheet
Cl.17, Schedule 5 of the Environmental Planning and Assessment Act 1979, reports to Council, S105001.002

Total number of properties tabled: 5

Report – April 2025

Summary table

Att. (A-F)	**Premises Specifics**	**Actions/ Recommendation**
A	Not applicable – Summary Sheet	Summary of clause 17, Schedule 5 matters tabled at Council meeting.
B	31 Market Street, Sydney	Premises inspected; matters raised have been rectified, no further action required.
C	1-73 Broadway, Ultimo	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
D	9-13 Hay Street, Haymarket	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
E	2-4 Cunningham Street, Haymarket	Premises inspected; owners have previously been issued with a Fire Safety Order; owners have also been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.
F	102 Miller Street, Pyrmont	Premises inspected; owners have been issued with corrective action correspondence; follow up compliance site inspections are to be undertaken to ensure fire safety works are satisfactorily completed.